	$ extsf{T}$ Ype	H H	Hits	Search Text	DBs	Time Stamp Comments	Comments
	BRS	. r1	9250	control\$4 with leak\$3 with system\$1	US- PGPUB; USPAT; TPO; JPO; DERWE NT; IBM_T	2007/01/23 15:32	
8	BRS	1.2	5 6	control\$4 with leak\$3 with system\$1 with (processor\$1 or microprocessor\$1 or CPU) with (code or coding or program\$5 or software)	US- PGPUB; USPAT; JPO; JPO; DERWE NT; IBM_T	2007/01/23	

Errors		
Error Definition		
	-	N

	Туре	#	Hits	Search Text	DBs	Time Stamp Comments	p Comment
m	BRS.	L3		control\$4 with leak\$3 with system\$1 with (flowmeter\$1 or (flow\$3 with meter\$1) with (processor\$1 or microprocessor\$1 or CPU) with (code or coding or program\$5 or software)	US- PGPUB; USPAT; JPO; DERWE NT; IBM_T	2007/01/23 15:34	m
4	BRS	1. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.	0	control\$4 with leak\$3 with system\$1 with (flowmeter\$1 or (flow\$3 with meter\$1) with stop\$4 with valve\$1 same (processor\$1 or microprocessor\$1 or CPU) with (code or coding or program\$5 or software)	US- FGPUB; USPAT; FPO; UPO; DERWE NT; IBM_T	2007/01/23 15:34	<u>m</u>

	m	
Error Definition		·
Err		

Туре	H	#	Hits	Search Text	DBs	Time Sta	) dwe	Stamp Comments
BRS	F 55	0		control\$4 with leak\$3 with system\$1 with (flowmeter\$1 or (flow\$3 with meter\$1) with stop\$4 with valve\$1 and (processor\$1 or microprocessor\$1 or CPU or computer\$1) with (code or coding or program\$5 or software)	US- PGPUB; USPAT; PPO; UPO; DERWE NT; IBM_T	2007/01/23 15:35	/23	
BRS	. 9 - I	<u> </u>	. 0	leak\$3 with system\$1 with (flowmeter\$1 or (flow\$3 with meter\$1)) with stop\$4 with valve\$1 and (processor\$1 or microprocessor\$1 or CPU or computer\$1) with (code or coding or program\$5 or software)	US- PGPUB; USPAT; JPO; DERWE NT; IBM_T	2007/01/23 15:35	/23	

Err	·	
Error Definition		
	ស	9

Type	#	Hits	Search Text	DBs	Time Stamp	Stamp Comments
BRS	L7	0	control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) with stop\$4 with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1) with (code or coding or program\$5 or software)	US- PGPUB ; USPAT ; JPO; DERWE NT; IBM_T	2007/01/23 15:35	:
BRS	L 8	13	control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and stop\$4 with valve\$1 and (processor\$1 or microprocessor\$1 or CPU or computer\$1) with (code or coding or program\$5 or software).	US- PGPUB; USPAT; FPO; JPO; DERWE NT; IBM_T	2007/01/23 15:36	·

Err		
Error Definition		
	7	ω

	Туре	#	Hits	Search Text	DBs	Time S	tamp	Time Stamp Comments
	BRS	년 6	7	control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and stop\$4 with valve\$1 and (processor\$1 or microprocessor\$1 or CPU or computer\$1) with (code or coding or program\$5 or software) and pipe\$1	US- PGPUB; USPAT; FPO; JPO; DERWE NT; IBM_T	2007/01/23 15:36	1/23	·
0	BRS	L10	<u></u>	control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1) with (code or coding or program\$5 or software) and pipe\$1	US- PGPUB; USPAT; TPO; UPO; UERWE NT; IBM. T	2007/01/23 16:16	1/23	

	Error Definition	Err
·	·	
C		

	Туре	#	=======================================	Hits	Search Text	DBs	Time	Stamp	Stamp Comments
BRS			<u></u>		control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1) with (code or coding or program\$5 or software or logic\$4) with (code state\$1) and pipe\$1	US- PGPUB; USPAT; JPO; DERWE NT; IBM_T	2007/	2007/01/23	
BRS	1	L12	8		control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or CPU or computer\$1) with (condition\$1 or status or state\$1) with pipe\$1	US- PGPUB; USPAT; JPO; DERWE NT; IBM_T	2007/	2007/01/23 15:44	

Err		
Error Definition		
	11	12

	Type	H #	Hits	Search Text	DBs	Time Stamp Comments	C	comments
m <sub>.</sub>	BRS	L13	. ~~~	control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or CPU or computer\$1) with control\$4 with (condition\$1 or status or state\$1) with pipe\$1	US- PGPUB; USPAT; JPO; UPO; UERWE NT; IBM_T	2007/01/23		-
4	BRS	L14		leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or CPU or computer\$1) with control\$4 with (condition\$1 or status or state\$1) with pipe\$1	US- PGPUB; USPAT; JPO; UPO; DERWE NT; IBM_T	2007/01/23	/23	

Err		
Error Definition		
	13	14

	Type	#	Hits	Search Text	DBs	Time Stamp Comments	Comments
15	BRS S	L15	4	control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1 or controller\$1 or control\$4 with (condition\$1 or status or state\$1) with pipe\$1	US- PGPUB  USPAT  TPO; JPO; DERWE  NT; IBM_T  DB	2007/01/23 15:45	
16	BRS	L16		control\$4 with leak\$3 with flow\$3 and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1 or controller\$1) with control\$4 with (condition\$1 or status or state\$1) with pipe\$1	US- PGPUB; USPAT; JPO; UPO; UERWE NT; IBM_T	2007/01/23 15:47	

Err		
Error Definition		
	15	16

Туре	#	Hits	Search Text	DBs	Time Stam	Time Stamp Comments
BRS	L17	2	control\$4 with leak\$3 with flow\$3 and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1 or controller\$1 with control\$4 with (condition\$1 or status or state\$1) with pipe\$1 and return\$3 with pipe\$1	US- PGPUB; USPAT; JPO; DERWE NT; IBM_T	2007/01/23	
BRS	L19	8	"20060287837"	US- PGPUB; USPAT; JPO; DERWE NT; IBM_T	2007/01/23 15:49	m

Brr		
Error Definition		
	17	18

	Туре	#	Hits	Search Text	DBs	Time	Stamp	Time Stamp Comments
. თ	BRS	, 1750	133	leak\$3 with flow\$3 and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1 or controller\$1) with control\$4 with (condition\$1 or state\$1) with pipe\$1 and return\$3 with	US- PGPUB; USPAT; JPO; DERWE NT; IBM_T	2007/	2007/01/23 16:05	

Err	
Error Definition	·
	6

.14
0
2.1
Version: 2
EAST
1/23/07,

	Type	# H	Hits	Search Text	DBs	Time	Stamp	Time Stamp Comments
50	BRS	121	0	leak\$3 with flow\$3 and (flowmeter\$1 or flow\$3 with meter\$1) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1 or controller\$1) with controls\$4 with (condition\$1 or state\$1) with pipe\$1 and return\$3 with	US- PGPUB; USPAT; TPO; JPO; DERWE NT; IBM_T	2007/	2007/01/23	
				pipe\$1				

. .

Err ors		
Error Definition	•	
	70	

	Type	#	Hits	Search Text	DBs	Time	Stamp	Time Stamp Comments
Н	BRS	L22	0	leak\$3 with flow\$3 and (flowmeter\$1 or flow\$3 with meter\$1) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1 or controller\$1) with control\$4 with (condition\$1 or state\$1) with pipe\$1 and (feedback or return\$3) with pipe\$1	US- PGPUB; USPAT; TPO; UPO; UPO; UBM_T	2007/	2007/01/23 16:07	

Err	
Error Definition	
	21

	Type	# T	Hits	Search Text	DBs	Time	Stamp	Time Stamp Comments
22 BRS	δ	L23	. ω	leak\$3 with flow\$3 and (flowmeter\$1 or flow\$3 with meter\$1) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or CPU or computer\$1 or controller\$1) with control\$4 with control\$4 with and (suppl\$3 or source) and (suppl\$3 or source)	US- PGPUB; USPAT; JPO; JPO; DERWE NT; IBM_T	2007/	2007/01/23	

E L	
Error Definition	
	22

	Type	#	Hits	Search Text	DBs	Time Stamp Comments	Comments
				leak\$3 with flow\$3 and (flowmeter\$1 or flows3	:		
					US-		
				(clos\$3 or open\$4 or	PGPUB		
				stop\$4) with valve\$1			- 31.
				and (processor\$1 or	USPAT		
				microprocessor\$1 or CPU	• •	2007/01/23	~
23	BRS	L24	0	or computer\$1 or	EPO;	2001/01/2: 16:00	<u> </u>
				controller\$1) with	JPO;	00.01	
				(condition\$1 or status	DERWE		
				or state\$1) with pipe\$1	'LN		
					IBM_T		
				with pipe\$1 and	DB _		
				(return\$3 or feedback)			
				with pipe\$1			

Err	
Error Definition	·
	23

# 1	Hits	Search Text	DBs	Time Stamp Comments	Comments
 5	ω	leak\$3 with flow\$3 and (flowmeter\$1 or flow\$3 with meter\$1) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1 or controller\$1) with (condition\$1 or status or state\$1) with pipe\$1 and (suppl\$3 or source) with pipe\$1	US- PGPUB; USPAT; TPO; JPO; DERWE NT; IBM_T	2007/01/23 16:12	
 9		control\$4 with (two-string\$2 or two adj string\$2) with pipe\$1 with installation\$1	US- PGPUB ; USPAT ; FPO; JPO; DERWE NT; IBM_T	2007/01/23 16:14	

Errors		
Error Definition		·
	24	25

	Туре	#	Hits	Search Text	DBs	Time Stamp Comments	Comments
26	BRS	L27	m	control\$4 with (two-string\$2 or two adj string\$2) with pipe\$1 with instal\$7	US- PGPUB; USPAT; FPO; JPO; DERWE NT; IBM_T	2007/01/23 16:14	
27	BRS	L28	&	control\$4 with (two-string\$2 or two with string\$1 with pipe\$1 with instal\$7	US- PGPUB ; USPAT ; JPO; DERWE NT; IBM_T	2007/01/23 16:15	,

Err	
Error Definition	
	 27

Type	#	Hits	Search Text	DBs	Time Stamp Comments	Comments
BRS	L29	ഹ	control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or CPU or computer\$1) with pipe\$1	US- PGPUB ; USPAT ; TPO; DERWE NT; IBM_T	2007/01/23 16:32	
BRS .	L30	43	"4883087" "4043355" "4825198" "6134949"	US- PGPUB; USPAT; JPO; UPO; UERWE NT; IBM_T	2007/01/23 16:27	

E N N N N N N N N N N N N N N N N N N N	·	
Error Definition		·
	8 7	50

•	Type	# H	Hits	Search Text	DBs	Time Stamp Comments	Comments
08	BRS	L31	<u></u>	130 and leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1))	US- PGPUB; USPAT; FPO; JPO; DERWE NT; IBM_T	2007/01/23 16:27	
31	BRS	L32	Н	control\$4 with leak\$3 with (flowmeter\$1 or (flow\$3 with meter\$1)) and (clos\$3 or open\$4 or stop\$4) with valve\$1 and (processor\$1 or microprocessor\$1 or computer\$1) with box\$2	US- PGPUB; USPAT; FPO; JPO; DERWE NT; IBM_T	2007/01/23 16:42	

Err		
Error Definition		
	30	31

	Type	#	Hits	Search Text	DBs	Time Stamp Comments	Comments
32	BRS	L33	212	702/51.ccls.	US- PGPUB  USPAT  EPO; JPO; DERWE  NT; IBM_T  DB	2007/01/23	
33	BRS	L34	1946	73/40.ccls.	US- PGPUB ; USPAT ; EPO; JPO; DERWE NT; IBM_T DB	2007/01/23 16:44	·

Err		·
Error Definition		
E1 Defi		
	32	8 8

	Type	#	Hits	Search	Text	DBs	Time Stamp Comments	Comments
						US- PGPUB		
•						; USPAT		
34	BRS	L35	503	73/49.1.ccls.		; EPO;	2007/01/23	<u> </u>
	·					JPO;	10:44	
						DERWE		
						'LN		-
				•		IBM_T		
						DB		
						ns-		
						PGPUB		
•								•
						USPAT		
							2007/01/23	~
35	BRS	136	1113	137/312.ccls.		EPO;	16:47	
						JPO;	•	
						DERWE		
						, LN		
						IBM_T		
						DB		

Err		
Error Definition		
	34	35

	Type	#	Hits	Search Text	DBs	Time Stamp Comments	Comments
36	BRS	L37	94	137/313.ccls.	US- PGPUB; USPAT; JPO; DERWE NT; IBM_T	2007/01/23 16:48	
37	BRS	T 38	83	137/314.ccls.	US- PGPUB; USPAT; JPO; UPO; DERWE NT; IBM_T	2007/01/23 16:48	

or Err		
Error Definition		
	36	37

	Type	#	Hits	Search Text	DBs	Time	camp	Stamp Comments
					US- PGPUB			
				•	; USPAT			
	ç (	( (	ן נ ט			2007/01/23	./23	٠
<u> </u>	BRS	الـ ج الـ ج	/ / 7	13//458.CCLS.	JPO;	16:48		
	-		•		DERWE			
					'LN			
					IBM_T			
			-		DB			
					us-			
					PGPUB			
					• .			
					USPAT			
					• •	7007/01	103	
6	BRS	L40	1294	137/557.ccls.		16:48	7 7 7	
						•		
					DERWE			
					, LN			
					IBM_T			
					DB			

Err ors		
Error Definition		
	38	9